| NO. OF COPIES RECEIVED |] | |
|---|--|---|
| DISTRIBUTION | - | Form C-103 Supersedes Old |
| SANTA FE | NEW FERE OF OIL YON FE PATION COMMISSI | |
| FILE | NEW MEXICO-UIL CONSERVATION COMMISSI | ION Effective 1-1-65 |
| U.S.G.S. | | |
| · | - FEB 2 0 1973 | Sa. Indicate Type of Lease |
| LAND OFFICE | | State X Fee |
| OPERATOR | | 5. State Oil & Gas Lease No. |
| | <u> </u> | K-3004 |
| IDO NOT USE THIS FORM FOR PR USE "APPLICAT | RY NOTICES AND REPORTS ON WELLS OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESE FION FOR PERMIT | SRIVOIR. |
| 1. OIL GAS WELL | OTHER- | 7. Unit Agreement Name |
| 2. Name of Operator | | 8, Farm or Lease Name |
| J.M. Huber Corpora | tion | Apache - State |
| 3. Address of Operator | | 9. Well No. |
| 1900 Wilco Buildin | g, Midland, Texas 79701 | 1 |
| 4. Location of Well | | 10. Field and Pool, or Wildcat |
| UNIT LETTER G, | 1980 FEET FROM THE North LINE AND 1980 | FEET FROM Wildcat |
| Rast | | |
| THELINE, SECTI | on 16 TOWNSHIP 238 RANGE 26E | NMPM. (() () () () () () () () () () () () () |
| , , , , , , , , , , , , , , , , , , , | 15. Elevation (Show whether DF, RT, GR, etc.) | |
| | | 12. County |
| | 3347.9 GL | Eddy |
| Check | Appropriate Box To Indicate Nature of Notice, R | eport or Other Data |
| NOTICE OF I | | UBSEQUENT REPORT OF: |
| | | |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON REMEDIAL WORK | ALTERING CASING |
| TEMPORARILY ABANDON | COMMENCE DRILLING OP | |
| PULL OR ALTER CASING | CHANGE PLANS CASING TEST AND CEMEN | LI PLOG AND ABANCONMENT |
| | OTHER Inter | mediate Casing X |
| OTHER | | ······································ |
| | | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled 12¹/₄" hole to 5408' in lime. Ran 173 joints, 5415.70', 9-5/8" casing bottom-to-top as follows: 55 joints, 1738.42', 40#, K-55, ST&C; 118 joints, 3677.28', 36#, K-55, ST&C with Baker guide shoe, automatic insert float and 5 centralizers located @ 5400', 5365', 5303', 5242' and 5179', float @ 5384', 9-5/8" casing set @ 5408'. Cemented with 1500 sx Lite Wate with 7¹/₂# salt per sx, and ¹/₄# celloflake per sx, tailed in with 300 sx Class "C". Good circulation until last 300 sx, then poor circulation, cement did not circulate. Plug down @ 5:15 A.M. CST 2/12/73. Nippled up BOP's and Hydril. Ran temperature survey 12 hours after plug down, top of cement @ 1200', W.O.C. 48 hours. Tested 9-5/8" casing, BOP's and manifold to 3000 psi for 30 minutes, held OK.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

| SIGNED James R. Sutherland | TITLE District Production Supt | •DATE 2/19/1973 |
|--|--------------------------------|-------------------|
| APPROVED BY W. A. A. A. C. CONDITIONS OF APPROVAL, IF ANY: | TITLE OIL AND GAS INSPECTOR | DATE FEB 2 2 1973 |