

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

JUL 6 1973

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p>SUNDY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p>
<p>1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole</p>		<p>5. State Oil & Gas Lease No. K-3004</p>
<p>2. Name of Operator J.M. Huber Corporation</p>		<p>7. Unit Agreement Name</p>
<p>3. Address of Operator 1900 Wilco Building, Midland, Texas 79701</p>		<p>8. Farm or Lease Name Apache - State</p>
<p>4. Location of Well UNIT LETTER G, 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 16 TOWNSHIP 23-S RANGE 26-E NMPM.</p>		<p>9. Well No. 1</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) 3347.9 GL</p>		<p>10. Field and Pool, or Wildcat Wildcat</p>
		<p>12. County Eddy</p>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER Delaware Cherry Canyon <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

RTD 12,000', 8-3/4" hole. Spotted thru D.P. 40 sx Plug #1 @ 11,361'; 35 sx Plug #2 @ 10,285'; 40 sx Plug #3 @ 8770'; 40 sx Plug #4 @ 8212'; & 50 sx Plug #5 @ 5338' (Form C-103 previously submitted and approved 4/6/73) together with Intention to Test Delaware Cherry Canyon thru perforations @ 2614-22', 2630-40' and 2670-85'. Notice of Intention, Form C-103, submitted and approved 5/25/73 for P & A of the Delaware Cherry Canyon. 10 sx cement plug set @ 2570, 60 sx cement plug set @ 1789', 70 sx cement plug set @ 664', and 10 sx cement plug set @ top, 4" steel dry hole marker installed. 1800' of 9-5/8" casing recovered. Job complete 6/30/73.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **James R. Sutherland**

TITLE **District Prod. Supt.**

DATE **7/5/73**

APPROVED BY

TITLE **OIL AND GAS INSPECTOR**

DATE **FEB 26 1974**

CONDITIONS OF APPROVAL, IF ANY: