

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN DDA DATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 04473 & NM 02887-D

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME James Ranch Unit	
2. NAME OF OPERATOR Belco Petroleum Corporation ✓		8. FARM OR LEASE NAME James Ranch Unit	
3. ADDRESS OF OPERATOR 2000 Wilco Building, Midland, Texas 79701 D. C. C.		9. WELL NO. 4	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2180' FSL & 330' FWL of Section 6, T-23-S, R-31-E, Eddy County, New Mexico		10. FIELD AND POOL, OR WILDCAT Undesignated Morrow Gas	
14. PERMIT NO. Dated 5-4-73		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3296' GR	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 6, T-23-S, R-31-E	
		12. COUNTY OR PARISH Eddy	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) Spud well & set casing <input checked="" type="checkbox"/>	
(Other) <input type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 20" hole on May 21, 1973, and drilled to depth of 485'. Ran 11 joints (489.92') of 16", 65#, H-40, ST&C, Range 3 casing. Set casing at 461' and cemented with 450 sacks Dowell "lite weight" with 7.5" salt per sack and 1/4" celoflex per sack, followed by 200 sacks Class "C" with 2% CaCl. Circulated approximately 65 sacks to pits. Plug down at 6:25 p.m. May 22, 1973. WOC 18 hours. Pressure tested casing to 600# for 30 minutes - held O.K.

RECEIVED

JUN - 4 1973

U. S. GEOLOGICAL SURVEY
ARTERIA, NEW MEXICO

RECEIVED

MAY 31 1973

U. S. GEOLOGICAL SURVEY
ARTERIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Glenn Cope TITLE District Engineer DATE May 29, 1973

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE DISTRICT ENGINEER DATE JUN 4 1973
CONDITIONS OF APPROVAL, IF ANY: