

ATTACHMENT: FORM C-105
NEW MEXICO OIL CONSERVATION COMMISSION

DRILL STEM TESTS

OPERATOR: J.M. Huber Corporation

LEASE & WELL NUMBER: Yates King #1

LOCATION: 1980' FS&WL Section 22, T-23-S, R-26-E,
Eddy County, New Mexico

DST #1, 11,540-730' (Morrow). 15 minute preflow, GTS 15 minutes,
TSTM. Packers failed 20 minutes into final flow.

IHP	6285#
PFP	873-833#
ISIP	5026#/1:00
FFP	833-852# (when packers failed)
FHP	6256#

DST #2, 11,515-730' (Morrow). Final flow on 1/4"choke GV 190
MCFPD, FTP 120 psi. Recovered 1000' WC + 209' GCDM.
Sample chamber pressure 3500 psi recpvered 31.5 CFG +
30 cc's DM.

IHP	6255#
PFP	671#/0:15
ISIP	4761#/1:15
IFP	731#/1:00
FFP	830#/1:00
FSIP	5004#/2:00
FHP	6196#
BHT	193 Degrees F