

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0353184

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Bowden Federal "25"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Crawford/Morrow

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 25, T24S, R26E

N.M.P.M.

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

RECEIVED

2. NAME OF OPERATOR

HNG OIL COMPANY

3. ADDRESS OF OPERATOR

P. O. Box 767, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

JUN 14 1973
OFFICE
ARTESIA, NEW MEXICO

1980' FSL & 660' FEL, Sec. 25, T-24-S, R-26-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3362' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Set Intermediate Casing

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled out from under intermediate 3-3-73.

Drilled 9-1/2" hole to 9200'. Ran 221 jts. 7-5/8", 29.70%, N-80 casing.

Cemented with 400 sx LW, 500 sx Class "H" cement. Plug down @ 1:45 A.M. 3-24-73.

WOC 6 hours. Tested casing w/1250# for 45 minutes; pressure held.

Cementing work done by Halliburton Services.

RECEIVED

JUN 13 1973

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

RECEIVED

JUN 13 1973

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

RR Fray

TITLE

Petroleum Engineer

DATE

6-4-73

(This space for Federal or State office use)

APPROVED BY

John C. Ruff

TITLE

DISTRICT ENGINEER

DATE

JUN 13 1973

CONDITIONS OF APPROVAL, IF ANY.