

A & A ENGINEERING SERVICE

P. O. BOX 3323

Midland, Texas 79701

BOTTOM HOLE PRESSURE REPORT

Operator J. M. Huber Corporation Lease Moore-Com Well No. 1
 Field Carlsbad, South Reservoir Morrow Datum _____
 Test Date August 8, 1973 Well Status Shut In Hours Shut In _____
 Tubing 2 7/8" Depth _____ End Open Packer 11482' S. N. _____
 Casing _____ Depth _____ Perf. 11515-11618' Total Depth _____

	Depth	Press. Lbs/Sq. In.	Δ Press.	Gradient Lbs/Ft.
Tubing Press. <u>3352# DWT</u>	Surface	3352		
Casing Press.	5000	3750	398	.080
Top of Fluid. <u>None</u>	10000	4145	395	.079
Top of Water. <u>None</u>	11166	4225	80	.069
Temp. @.....°F.....	11366	4238	13	.065
Elev. KB.....Gl.....	11566	4251	13	.065
Last Test Date. <u>Initial</u>	0	0		
Press. Last Test.....	11566	4251		
Change.....Per Day.....				
Inst. No. <u>7445</u> Cal. <u>73-3</u>				
Tested By. <u>Spruell</u>				
Calcu. By. <u>Arnett</u>				
Prod. Index.....Bbls/day/lb.....				
Drop.....				
Cumulative prod.				

Ctr. Of Perf.

Remarks: