

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

NM 0475051

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ Dry **RECEIVED**

2. NAME OF OPERATOR

Pennzoil Company

3. ADDRESS OF OPERATOR

P. O. Drawer 1828 - Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1750 FSL & 1650 FWL

APR 29 1974

O.C.C.
ARTESIA, OFFICE

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Allied -B-

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

White City Penn (Morrow)

11. SEC., T., R., M., OR B.L. AND SURVEY OR AREA

Sec. 22, T-24-S, R-26-E

12. COUNTY OR PARISH 13. STATE

Eddy

N. M.

14. PERMIT NO.

15. ELEVATIONS (Show whether DE, RT, GR, etc.)

3319.5' G.L.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other) Running 9 5/8" casing

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

6-18-73 Total depth 5,375'
Ran logs from total depth to surface casing.
Set 9 5/8" casing @ 5,375' & cemented w/1,260 sx.

6-19-73 Ran Temperature survey, T/cement @ 1,300' from surface.
Installed BOP and tested casing to 2,000 psi for 30 minutes -O.K.
Drill out with 7 7/8" bit.

18. I hereby certify that the foregoing is true and correct

SIGNED

J. C. Raney

TITLE

Petroleum Engineer

DATE

4-23-74

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

