

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR
(Other instructi
verse side)FE*
reForm approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0413245

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

O'Neill -B-

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR B.LK. AND
SURVEY OR AREA

Sec. 10, T-24-S, R-26-E

12. COUNTY OR PARISH

Eddy

13. STATE

N. M.

1.

OIL
WELL ☐ GAS
WELL ☒ OTHER

RECEIVED

2. NAME OF OPERATOR

Pernzoil Company

AUG 14 1973

3. ADDRESS OF OPERATOR

P. O. Drawer 1828 - Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

2300' FSL & 1980' FEL of Section 10, T-24-S, R-26-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3325' G.L.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

Commenced drlg. & set csg.

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

X

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7-28-73 Spud well at 6:00 P.M. 7-28-73

7-29-73 T.D. 400' - Ran 13 jts. of 13 3/8", H-40, 48# casing - set at 400' in 17 1/2" hole. Cemented w/450 sx Class "H" cement with 1/4# flo-
cele per sack and 2% CaCl. Circulated out 50 sx. Plug down at 12:00 noon 7-29-73. W.O.C.

7-30-73 W.O.C. 24 hrs. - Tested casing to 1,350 psi for 30 minutes. Held O.K. Drill out 12 1/4" hole.

RECEIVED
AUG-9 1973
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Petroleum Engineer

DATE 8-8-73

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side