		•		
NO. OF COPIES RECEIVED	12		-	
DISTRIBUTION				Form C-103
SANTA FE	1		NEW HEXICO OUL CONCEDURATION	Supersedes ()ld C-102 and C-103
FILE	1		NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
U.S.G.S.				
LAND OFFICE				5a. Indicate Type of Lease
OPERATOR	1		•	State Fee X
				5. State Oil & Gas Lease No.
(DO NOT USE THIS FOUSE	SUI	DR	Y NOTICES AND REPORTS ON WELLS POSALS TO DRILL OR TO DELEVEN OF FLUG BACK TO A DIFFERENT RESERVOIR. ION FOR PERMIT (FORM C-101) FCP SUCH PROPOSALS.)	
	ι Ϊ			7. Unit Agreement Name
2. Name of Operator	ι <u></u>			
• • • • • • • • • • • • • • • • • • • •		_		8. Farm of Lease Hame
Mesa Petrole	um (<u>Co.</u>	SEP 2 7 1973	Reddy Com
Box 2009 Ama		~	JEF 2 / 1979	9. Well No.
4. Location of Well		<u>,</u>	1exas 79105	1
. т			©, C, C,	10. Field and Pool, or Wildcat
UNLY LETTER	•	10	280 FEET FROM THE SOUTH AND 1980 FEET FROM	S. Carlsbad (Atoka)
THE L	INE, SE	CTION	8 235 RANGE 27E NMPM.	
	7777	\overline{n}		
	////	$\left(\right) \left(\right) $	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
16.	7777	177	3167'GL	Eddy
	Chec	k A	ppropriate Box To Indicate Nature of Notice, Report or Oth	er Data
NOTIC	E OF	' IN T	TENTION TO: SUBSEQUENT	REPORT OF
	1			
PERFORM REMEDIAL WORK))		PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PULL OR ALTER CASING			COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
L			CHANGE PLANS CASING TEST AND CEMENT JOB	
OTHER			OTHER Abandonment of	Morrow, PerforationX
			& Stimulation of Ato	
7. Describe Proposed or Com	pleted	Oper	ations (Clearly state all pertinent details and size particulation of 1100	

work) SEE RULE 1103.

Morrow was perforated 11,655-658, 11,682-688, 11,758-764 and 11,800-808'. Morrow was treated with 2500 gallons of 7 1/2% MS acid. After recovering load, well was still being swabbed. Recovery was 20-25 BWPD and 25-100 MCF/D. Morrow was abandoned as uncommercial by setting a wireline plug in the packer at 11,579'. Dumped 1 1/2 sacks sand and 7 sacks Class H cement on top of plugged packer. Calculated PBTD 11,511'.

Perforated Atoka 10,870-876', 10,839-844' and 10,791-794'. Atoka flowed at 1.6 MMCF/D rate with 660 psi separator pressure. Acidized with 2000 gals. 15% and flow stabilized @ 3.5 MMCF/D rate with 660 psi separator back pressure. Fracture treated well with 14000 gals. acid frac and 16,000# of 20-40 sand and 2000# of 12-20 glass beads. Flow stabilized at 6.2 MMCF/D rate with 600 psi separator pressure.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.
--

SIGNED Michael P. Houston	mu Production Engineer	DATE Sept. 20, 1973
APPROVED BY W. a. Gressett	TITLE OIL AND GAS INSPECTOR	SEP 27 1973