

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42 R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0399637

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

RECEIVED

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ DRILLING	JUL 3 1973
2. NAME OF OPERATOR Amoco Production Company	
3. ADDRESS OF OPERATOR BOX 68, HOBBS, N. M. 88240	O. C. C.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1650' FSL x 1650' FEL Sec. 15 (Unit J, NW 1/4 SE 1/4)	ARTESIA, NEW MEXICO
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3937' G.L.

7. UNIT AGREEMENT NAME SLATER FED. GAS COM
8. FARM OR LEASE NAME 1
9. WELL NO. 1
10. FIELD AND POOL, OR WILDCAT BACK TANK - LOWER MORROW
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 15-23-24 NMPM
12. COUNTY OR PARISH EDDY
13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Cactus Drilling Corp spudded 17 1/2" hole 3:00 PM 6-21-73.
On 6-22-73 13 7/8" OD 48" H-40 casing was set @ 278'
w/ 325 S Incon + 2% CACL + 1/4" / 5X FLOSEAL. CEMENT Circ.
after WOC 18 hours tested csg @ 1200 psi for 30 min.
Test O.K.
Reduced hole to 12 1/4" @ 378' and resumed drilling.

RECEIVED

JUN 27 1973

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Loy R. Yorkum

TITLE ADMINISTRATIVE ASSISTANT

DATE JUN 25 1973

(This space for Federal or State office use)

APPROVED BY

John A. Kraft

TITLE

DISTRICT ENGINEER

DATE

JUN 29 1973

CONDITIONS OF APPROVAL, IF ANY:

4- USGS-ART
1- DIV
1- SUSP
1- RRY

*See Instructions on Reverse Side