(Copy 4 SF

Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

N. M. O. C. C. COPY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.
NM-039967

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☐ OTHER DRILLING

7. UNIT AGREEMENT NAME
SLATER FEDERAL GAS COM

2. NAME OF OPERATOR
Amoco Production Company

SEP 10 1973

8. FARM OR LEASE NAME

3. ADDRESS OF OPERATOR
BOX 68, HOBBS, N. M. 88240

O. C. C.
ARTESIA, OFFICE

9. WELL NO.
1

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
1650' FSL x 1650' FEL Sec. 15 (UNIT J, NW/4 SE/4)

10. FIELD AND POOL, OR WILDCAT
ROCK TANK

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
15-23-~~27~~ 24 NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3954' RDB

12. COUNTY OR PARISH
EDDY

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐	WATER SHUT-OFF	☒	REPAIRING WELL	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐	FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☐	SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
REPAIR WELL	☐	CHANGE PLANS	☐	(Other)			☐
(Other)			☐				

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 6-29-73, 8 5/8" OD 24-32# Casing was set @ 2775' x 910 Sx. Low Density + 1% CACL x 1/4# Flocel + 5# Gilsonite/sx + 200 sx class C + 2% CACL. Cement circ. After WOC 18 hours, tested casing w/ 1500 psi for 30 min. Test OK.

Reduced hole to 7 7/8" @ 2775' and resumed drilling.

RECEIVED
SEP - 6 1973
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Kay R Yokum TITLE ADMINISTRATIVE ASSISTANT DATE 7-3-73

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
SEP - 6 1973
R. L. BEEKMAN
ACTING DISTRICT ENGINEER

Or 4- USGS Art
1- Div
1- Sus D
1- RRJ
1- Flagg - Redform

*See Instructions on Reverse Side