

Details of bop test



Exxon Company, U.S.A.

Gas Unit Combo #41

3/12/74

Contractor: Noble Drlg. Rig OW77

Test by Yellow Jacket Tools and Services, Inc.



The above is a transposition of the pressure recorder charts covering test to the blowout control equipment in service on your well drilling in the Carlsbad, New Mexico Area, Midland District, Texas. Test was made with test plug landed in casing head and with test packer with the following test results:

Arrived location - rig nipping up.