


Champlin Petroleum Company
 Pecos Federal No. 1
 Unit C, Sec. 1-T22S-R27E
 Eddy County, New Mexico
 Strawn Perforations 10,580-10,608
 Date of Test: 3-27-74



$Q_1 = 1980$ MCFD $\text{Log} Q_1 = 3.29667$
 $Q_2 = 262$ MCFD $\text{Log} Q_2 = 2.41830$
 $n = 0.878$