WY OIL CONS. COMMISSION

,

•

Artesia, NM 88210

| Form 9–331 Dec. 1973 | Form Approved. Budget Bureau No. 42–R1424 |
|---|--|
| UNITED STATES | 5. LEASE |
| DEPARTMENT OF THE INTERIOR | NM-027994-D |
| GEOLOGICAL SURVEY | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
| SUNDRY NOTICES AND REPORTS ON WELLS | 7. UNIT AGREEMENT NAME |
| (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) | 8. FARM OR LEASE NAME SEP 2 4 1981 |
| 1. oil gas 💬 | Federal "RR" Com |
| well well to other | 9. WELL NO. |
| 2. NAME OF OPERATOR | 1 ARTESIA CLUE |
| Mobil Producing TX. & N.M. Inc. / | 10. FIELD OR WILDCAT NAME |
| 3. ADDRESS OF OPERATOR | South Carlsbad Morrow |
| 9 Greenway Pl., Ste 2700, Houston, Texas 77046 | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA |
| LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) | Sec. 24, T-23-S, R-26-E |
| AT SURFACE: 660 FSL & 1980 FWL | 12. COUNTY OR PARISH 13. STATE |
| AT TOP PROD. INTERVAL: Same as surface | Eddy New Mexico |
| AT TOTAL DEPTH: Same as surface | 14. API NO. |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, | |
| REPORT, OR OTHER DATA | 15. ELEVATIONS (SHOW DF, KDB, AND WD) |
| DECUSET FOR APPROVAL TO CURRENT REPORT OF | 3234 GR |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: | |
| | STATES CON |
| SHOOT OR ACIDIZE | 24W29 [[]] |
| | (NOTE: Report esults of multiple completion or zone |
| PULL OR ALTER CASING U JUST SEP 2 | 1 1981 / [] |
| | |
| ABANDON* | & GAS |
| | GICAL SURVEY NEW MEXICO |
| 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinen | e all pertinent details, and give pertinent dates, irectionally drilled, give subsurface locations and |
| 9-1-81 MIRU Lee Swab Serv Ut, SW 8 bbls fluid, open to Baker D pkr @ 11,440. | /6 hrs, ran SW, found tbg |
| 9-2-81 Western Co attm to load csg 420 bbls 22 ran SW, FL @ 3000, SW 14 bbl fluid $2\frac{1}{2}$ 1 | |
| 9-3-81 S 37 bbls wtr 3½ hrs, FL standing @ 300 Permian WS Ut, NU BOP, rel from Baker 1 2-3/8 tbg, took 35,000 over pull to put clutch repair. | D pkr @ 11,440, pull 30' |
| Subsurface Safety Valve: Manu. and Type | Set @ Ft. |
| 18. I hereby certify that the foregoing is true and correct | |
| | ent |
| | ent_ date81 |
| ACCEPTED FOR RECENTSpace for Federal or State offi | ice use) |
| APPROVED BY ACCEPTED FOR RECEARD CONDITIONS OF APPROVAL IF ANY: | DATE |
| CONDITIONS OF APPROVAL, IF ANY | |
| SEP 2 2 1981 | |
| U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICOPE Instructions on Reverse S | šide |