

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Drawer DD
Artesia, NM

89219
LEASE
NM-027994-D

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME RECEIVED

8. FARM OR LEASE NAME
Federal RR Com DEC 15 1981

9. WELL NO.
1 O. C. D.

10. FIELD OR WILDCAT NAME
South Carlsbad Morrow

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 24, T23S, R26E

12. COUNTY OR PARISH
Eddy

13. STATE
New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3234 GR

C/SF
SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR
Mobil Producing TX. & N.M. Inc.

3. ADDRESS OF OPERATOR
9 Greenway Pl., Ste 2700, Houston, TX 77046

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660 FSL & 1980 FWL
AT TOP PROD. INTERVAL: Same as surface
AT TOTAL DEPTH: Same as surface

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

☐
☐
☒
☐
☐
☐
☐
☐
☐

RECEIVED
OCT 15 1981

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

9-24-81 Rel Permian WS Ut, Western Co. press csg 500, acidized Morrow perfs 11,512-11,875, 54 holes, down 203/8 tbg 100,000 SCF N2 pad, 10,000 gals 7-1/2% Fe Hcl acid w/360,000 SCF N2, 100 RCNBS, treating press 5000-5700, AIR 2.5 BPM, no ball action, flushed w/120,000 SCF N2, ISIP 5650, 10 min 5400, job compl @ 11:45, F1 120 BLW & died/8 hrs RU lee sw serv ut.

10-5-81 RU Permian Serv Co. Ut. Bled well to zero, remove tree, install BOP.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED R. L. Hogan TITLE Authorized Agent DATE 10-12-81

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

DEC 14 1981
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO