

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION  
**RECEIVED**

JUN 21 1974

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

**SUNDRY NOTICES AND REPORTS ON WELLS O. C. C.**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator <b>Union Oil Company of California</b> ✓	8. Farm or Lease Name <b>Walterscheid Com.</b>
3. Address of Operator <b>P.O. Box 671 - Midland, Texas 79701</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>N</b> <b>840</b> FEET FROM THE <b>south</b> LINE AND <b>1980</b> FEET FROM THE <b>west</b> LINE, SECTION <b>10</b> TOWNSHIP <b>22-S</b> RANGE <b>27-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Undesignated Morrow Gas</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3072.5' GR</b>	12. County <b>Eddy</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**3-6-74 through 3-21-74 Drilled 12½" hole to 5370'**

Ran & cemented 5349' 9-5/8", 47#, N-80 casing at 5368' with 2200 sx Dowell Lightweight followed by 500 sx Class "H". Cement did not circulate. Cemented 9-5/8" x 13-3/8" annulus with 350 sx Dowell Lightweight. Waited on cement 18 hours. Tested casing and B.O.P. to 1500 psi. for 30 minutes. OK. Started drilling new 8½" hole at 9:00 AM, March 23, 1974.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* TITLE District Drilling Supt. DATE June 18, 1974  
APPROVED BY *[Signature]* TITLE OIL AND GAS INSPECTOR DATE JUN 24 1974  
CONDITIONS OF APPROVAL, IF ANY: