

Details of bop test

INEXCO Oil Company


Dark Canyon State #1

4/1/74


Contractor: Moran Drlg. Rig 7

Test by Yellow Jacket Tools and Services, Inc.

=====Transposition of the pressure recorder charts=====



=====Transposition of the pressure recorder charts=====



The above is a transposition of the pressure recorder charts covering test to the blowout control equipment in service on your well drilling in the Dark Canyon, New Mexico Area, Houston District, Texas. Test was made with test plug landed in casing head with the following test results:

Arrived location - rig waiting on ring gasket.

Waiting on rig.