



Details of bop test      AMOCO Production Company      Trails Canyon Unit #1      6/13/74

Contractor: Noble Drlg. Rig N-83      Test by Yellow Jacket Tools and Services, Inc.

=====Transposition of the pressure recorder charts=====



=====Transposition of the pressure recorder charts=====



The above is a transposition of the pressure recorder charts covering test to the blowout control equipment in service on your well drilling in the Sitting Bull Falls, New Mexico Area, Hobbs District, New Mexico. Test was made with test packer landed in top of casing with the following test results:

Arrived location - rig nipping up rotating head.

Waiting on rig.