

Details of bop test



Morris R. Antweil

Bear #1

10/9/74

Contractor: Delta Drlg. Rig 60

Test by Yellow Jacket Tools and Services, Inc.



The above is a transposition of the pressure recorder charts covering test to the blowout control equipment in service on your well drilling in the Carlsbad, New Mexico Area, Hobbs District, New Mexico. Test was made with test plug landed in casing head with the following test results:

Arrived location - rig nipping up.