

Form 9-331  
(May 1963)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0540294

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL ☐ GAS ☒ OTHER ☐

Dry Hole

RECEIVED

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR

Coquina Oil Corporation

JAN 24 1975

8. FARM OR LEASE NAME

Exxon B Federal

3. ADDRESS OF OPERATOR

200 Bldg. of Southwest, Midland, Texas 79701

O. C. C.

ARTESIA, OFFICE

9. WELL NO.

1

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.)

At surface 1980' FEL &amp; 660' FNL, Sec. 29

10. FIELD AND POOL, OR WILDCAT

Und. Delaware

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 29, T23S, R26E

14. PERMIT NO.

30-015-21162

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

G.L. 3414'

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☒(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Drilled a 7 7/8" hole to a total depth of 2100'. Logs and drill stem tests indicated a dry hole. Plugged the subject well as follows:

Plug No.	No. Sxs.	From - To
1	25 sxs. CT. C	1700 - 1800
2	25 sxs. C1. C	1558 - 1658
3	25 sxs. C1. C	530 - 630
4	10 sxs. C1. C	0 - 10

Plugging complete @ 9:00 P.M., May 16, 1974.

RECEIVED

18. I hereby certify that the foregoing is true and correct

SIGNED

D. C. Radtke (D.C. Radtke)

TITLE

Engineer

DATE 6-4-74

(This space for Federal or State office use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

JAN 23 1975

L. BEEKMAN  
ACTING DISTRICT ENGINEER

\*See Instructions on Reverse Side