

WELL WORK REPORT

Page 17 of _____

Lease Name WOOD CANYON UNITWell Number 1

Location _____

Elevation _____ Perm. Datum _____

Down Hole
Condition
(after work)

Reason for Work _____

<u>Date</u>	<u>Operation</u>
9-3-74	<u>Making trip @ 11,205' (+41') for Bit #19 - 6 1/8 Smith F-5. Bit #18-6 1/8 Smith F-5 made 337' in 55 hours. Ph 10; Fresh water cost \$206.70</u>
9-4-74	<u>Drlg @ 11,300' Lm (+95'). 5'/hr. Bit #19 Smith 6 1/8" F-5 in @ 11,205'. Fresh water cost \$159.10, Brine cost \$165.30.</u>
9-5-74	<u>Drlg @ 11,490'. Lm and Sh (+190'). Bit #19 in At 11,205', 41½ hours. Has cut 285'. Mud cost \$9.30, MCTD \$12,645.11.</u>
9-6-74	<u>Drlg @ 11,556. Sh and Lm (+66'). Made a trip @ 11,546' for Bit #20 - 6 1/8" Reed F-73. Started out of hole @ 4:00 p.m, back on bottom @ 1:30 a.m. Bit #19 made 341' in 48 hours. CL 175,000. Fresh water cost \$193.80, Brine cost 187.60, Mud cost \$114.30, MCTD \$12,759.41.</u>
9-7-74	<u>Drlg @ 11,621. (+65'). Bit #20 in @ 11,546', made 75' in 22½ hours. Vis 35, yield point 20, Ph 8.5, WL 2.4, CL 142,000. Mud cost \$2943.84 MCTD \$13,703.25.</u>
9-8-74	<u>Drlg @ 11,655'. Sd & Sh (+34'). Made a trip @ 11,632 for bit #21 - 6 1/8" Security M88F @ 4:00 p.m. on bottom @ 12:00 midnight. Bit #20 made 86' in 36½ hours. Vis 37, WL 6, yield point 20, Gell 0/1, . Strap drill pipe made +15' correction.</u>
9-9-74	<u>Drlg @ 11,764. (+109') Bit #21 in @ 11,632, has made 132' in 32½ hours. Vis 36, Ph 8, WL 5, CL 144,000. Drilling breaks 11,751-60 and 11,702-715.</u>
9-10-74	<u>Making trip for DSI from 11,545-11,815. Drilled to 11,815. (+54'). Mixed mud and conditioned hole until 11:15 p.m., out of hole @ 4:30 a.m. Made up test tool, started in hole with test tool @ 7:45 this a.m. vis 36, Gell 1/2, WL 4, CL</u>

Signed _____