NO. OF COPIES RECEIVED	· ·			Form C-10	
DISTRIBUTION	•		•	Supersede. C+102 and	
SANTA FE	NEW MEXICO	OIL CONSERVATION	COMMISSION	Effective	
FILE /					
u.s.g.s.		9 -1 24		5a. Indicate T	ype of Lease
LAND OFFICE		R €	CEIVED	State X	Fce
OPERATOR /				5. State Oil &	Gas Lease No.
	,		1AR 9 - 1979	K-4101	
SUNDR 100 NOT USE THIS FORM FOR THE	Y NOTICES AND REP	PORTS ON WELLS	FERENT RESERVOIR.		
OIL X GAS WELL WELL	OTHER.		O. G. G.	7. Unit Agrees	ment None
Amoco Production			······································	South	Rock Tank Gas Cor
. Address of Cherater		70006		9. Well No.	OCK TATIK Gas Cor
P.O. Drawer "A",	Levelland, lexas	5 79336		1	Feel, or Wilderst
UNIT LETTER	1980 FEET FROM THE	North LINE AND	1980 FEET FROM	1	Springs
East	2 TOWNS	24-5	24-E		
ciac, secil		- AAYO	ANPX.	Milli	
	15, Elevation (S 3979	Show whether DF, RT, GR <b< td=""><td>, etc.)</td><td>Eddy</td><td></td></b<>	, etc.)	Eddy	
	777777				77/7/7/7/7/7
Check .	Appropriate Box To	Indicate Nature of 3	Notice, Report or Ot SUBSEQUEN		.e.,
NOTICE OF III	VIENTION TO.		SOBSEQUEN	REPORT	r.
PERFORM REMEDIAL WORK	PLUG AND	ABANDON REMEDIAL	work	A :	TERING CABING
Ħ			DRILLING OPNS.		G AND ABANDONMENT X
TEMPORARILY ABANDON	SULPET OF	 1	;====	00,	G AND ABANDONMENT
FULL OR ALTER CASING	CHANGE PL		ST AND CEMENT JOB		<u></u>
	•	OTHER			
CTHER		<u></u>			
Moved in casing p casing. Pulled 3 WOC 6 hours and t 2829'-2729'. WOC Erected P X A mar ready for inspect	1900' casing. Sp tag top of cement C 6 hours and tag rker. Cleaned an	otted 100' ceme at 3850'. Spo top of cement	nt in and out of tted 100' cement at 2729'. Set 20	casing 39 in and ou cement t	50'-3850'. it of 9 5/8" csg.
PPROVED BY THE STATE OF ANY	above is true and complet	,	rative Supervisor	DATE	arch 7, 1979 APR 2 0 1979
0+4-NMOCD,A 1-S	Susp 1-Houston	1-RWA 1-Un	ion		