. C COPIES RECEIVED	13			Form C-103
TRIBUTION				Supersedes Old
FE	+			C-102 and C-103
	+-;+		NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE			RECEIVED	
U.S.G.S.				Sa. Indicate Type of Lease
LAND OFFICE				State X Fee
OPERATOR			SEP - 9 1974	5. State Oil & Gas Lease No.
				K-6600
(DO NOT USE THIS F USI	SUN		Y NOTICES AND REPORTS ON WELLS	
1.			ARTEEN	7. Unit Agreement Name
OIL GAS	LΧ		OTHER-	Nash Unit
2. Name of Operator				8. Farm or Lease Name
Mesa	Petr	ole	eum Co. 🗸	Nash Unit
3. Address of Operator				9. Well No.
P. O.	Box	20	009, Amarillo, Texas 79105	1
4. Location of Well				10. Field and Pool, or Wildcat
н		1	1980 FEET FROM THE North LINE AND 660 FEET FROM	Wildcat
UNIT LETTER			FEET FROM THE INOI LINE AND	
Fact			13 <b>23</b> C 20F	$\boldsymbol{\lambda} = \boldsymbol{\lambda} = $
THE LIASL	LINE, S	ECTIC	DN 13 TOWNSHIP 235 RANGE 29E NMPM.	
kuuuuuu	1111	$\overline{T}$	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
$\mathbf{\nabla}$	////	())	3005 GR, 3024 RKB	Eddy
	7777	$\overline{77}$		
			Appropriate Box To Indicate Nature of Notice, Report or Oth	
ΝΟΤΙ	ICE O	F IN	TENTION TO: SUBSEQUENT	REPORT OF:
-				
PERFORM REMEDIAL WORK			PLUG AND ABANDON	ALTERING CASING
TEMPORARILY ABANDON			COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING			CHANGE PLANS CASING TEST AND CEMENT JOB	
			OTHER	
OTHER		<u> </u>		
-				

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Report submitted to supercede previous reports on 10 3/4" casing job and cement test.

Drilled to 3325' on 8-1-74. Ran 76 jts 10 3/4" 40.5# K-55 ST&C casing to 3325' RKB. Installed Dowell guide shoe with insert float in top of first joint; centralizers on 1st, 3rd, & 5th collars. Cemented with 1113 sx cement, 2% lo-dense w/5# gilsonite + 1/4# cello flake followed by 200 sx Class "C" neat. Had good returns throughout cementing operations, did not circulate cement. Bumped plug at 7:50 pm 8-1-74. Found cement at surface. Cement fell back while filling annulus with ready-mix. Used total of 14 yards of cement to fill to surface while cement was settling. Cut off casing in 11 hrs and WOC 29 hrs, then tested csg to 800 psi. 30 min. - OK.

IGNED_ Michael P. Mourton	Production Engineer	Sept. 5, 1974
PROVED BY W. a. Gressett	TITLE OIL AND GAS INSPECTOR	SEP 1 0 1974