

GUEVA UNIT #1  
SECTION 6, T23S, R26E  
Eddy County, New Mexico

December 27, 1974	Drilled from 375' to 378' lime and anhydrite.
December 28, 1974	Drilled from 378' to 380' lime and anhydrite.
December 29, 1974	Drilled from 380' to 382' lime and anhydrite.
December 30, 1974	Drilled from 382' to 385' lime and anhydrite.
December 31, 1974	Drilled from 385' to 387' lime and anhydrite.
January 1, 1975	Drilled from 387' to 390' lime and anhydrite.
January 2, 1975	Drilled from 390' to 393' lime and anhydrite.
January 3, 1975	Drilled from 393' to 395' lime and gyp. (problems with hole caving.)
January 4, 1975	Drilled from 395' to 397' lime and gyp. (problems with hole caving.)
January 5, 1975	Drilled from 397' to 400' lime and gyp. (problems with hole caving.)
January 6, 1975	Drilled from 400' to 403' lime and gyp.
January 7, 1975	Drilled from 403' to 406' lime and gyp.
January 8, 1975	Cleaning out.
January 9, 1975	Cleaning out.
January 10, 1975	Drilled from 406' to 408' lime and gyp.
January 11, 1975	Drilled from 408' to 410' lime and gyp.
January 12, 1975	Drilled from 410' to 412' lime and gyp.
January 13, 1975	Drilled from 412' to 414' lime and gyp.
January 14, 1975	Drilled from 414' to 417' lime and gyp.
January 15, 1975	Drilled from 417' to 420' lime and gyp.
January 16, 1975	Drilled from 420' to 423' lime and gyp.
January 17, 1975	Cleaning out.
January 18, 1975	Cleaning out.
January 19, 1975	Cleaning out.
January 20, 1975	Cleaning out.
January 21, 1975	Cleaning out.
January 22, 1975	Cleaning out.
January 23, 1975	Cleaning out.

RECEIVED

JAN 27 1975

O. C. C.  
ARTESIA, OFFICE