

Daily Report

Workover & Recomplete in Morrow Sands

Cueva Unit #1
Sec. 6-T23S-R26E
Sheep Draw Field
Eddy County, New Mexico

4/25/96 6:00AM Star Tool on location.
1 run could not get down below 200'
7:05AM put fishing tool on, went after, sat down on at
200', pulled out.
7:25AM out with jars cups and no go.
7:40AM Rigged up swab.
1 run fluid level 3800'
2 run fluid level 3800'
3 run fluid level 5100'
4 run fluid level 6300'
5 run fluid level 6900'
6 run fluid level 8000'
7 run fluid level 8600'
8 run fluid level 9600' to PF nipple
9 run fluid level 10,000' to PF nipple. left
flowing to pit. 1 hour.
10 run fluid level 10,000' to PF nipple.
11 run fluid level 10,700' to PF nipple.
2:25PM shut down put on pipeline.

4/26/96
7:10AM 365 psi flowing on pipeline, on 6/64 choke
sold to 7:15AM.
7:30AM Started swabbing
1 run fluid level 4000'
2 run fluid level 5100'