

Daily Report

Workover & Recomplete in Morrow Sands

Cueva Unit #1
Sec. 6-T23S-R26E
Sheep Draw Field
Eddy County, New Mexico

=====

4/21/96 9:00AM 840 PSI flowed on 12/64 for 30 min, 20 psi flowing pressure.
1 run fluid level 2800' out with 1000'
2 run fluid level 3800' out with 800'
3 run fluid level 4200'
4 run fluid level 4500'
5 run fluid level 3400'
6 run went to 8000' w/swab out with 1200'
7 run went to 9500' w/swab out with 1400'
8 run went to PF nipple
left flowing to pit for 1 hour. Went back in on 9th run after 1 hour
9 run went to PF nipple, did not feel any fluid out with -0-
10 run went to PF nipple, out with 3000' fluid.
8:00PM shut down

4/22/96 7:00AM 600 PSI put to pit 10/64 choke. for 20 minutes wide open blew down 200 psi in 5 minutes.
1 run 2800' from surface.
9:08AM Rigged down Congo Swab Unit.
9:55AM Rigged up Pride Swab Unit
1 run fluid level 2600'
2 run fluid level 3800'
3 run fluid level 5100'
4 run fluid level 5300'
5 run fluid level 5700'
6 run fluid level 6300'
7 run fluid level 6900'
8 run fluid level 8000'
9 run fluid level 8000'
10 run fluid level 8600' went to 10,000'
11 run fluid level 10,100' went to PF nipple
12 run went to PF nipple.
3:15PM to 4:15PM shut in for 1 hour. 35 psi wellhead.
13 run fluid level 8000' went to 10,000'
4:50PM shut in for night.