CUEVA UNIT #1 SECTION 5, T23S, R26E EDDY COUNTY, NEW MEXICO

- July 5, 1975From 11044' to 11071' in lime & shale8 hrs. drilling.From 11071' to 11104' in lime & shale8 hrs. drilling.July 7, 1975From 11148' to 11202' in lime & shale8 hrs. drilling.July 7, 1975From 11202' to 11255' in lime & shale8 hrs. drilling.July 8,1975From 11296' to 11323' in lime & shale8 hrs. drilling.July 8,1975From 11296' to 11323' in lime & shale8 hrs. drilling.
- July 9, 1975 From 11379' to 11406' in lime & shale 6 3/4 hrs. drilling. 3/4 hrs. dev. survey on w.L. ½ hr. drilling. From 11406' to 11430' in shale & Sand ¼ hr. drilling %hr. Jet Shale Pit 7½ hrs. drilling. From 11430' to 11455' in shale & lime. 8 hrs. drilling.

From 11348' to 11379' in lime & shale 8 hrs. drilling.

July 10, 1975 From 11455' to 11480' in shale & lime. 8 hrs. drilling. From 11480' to 11502' in shale & sand. 8 hrs. drilling. From11502' to 11535' in liem & shale. 8 hrs. drilling.

RECEIVED

JUL 1 4 1975

O. C. C.