

N. M. O. C. C. Copy
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIP
(Other instruction
verse side)

TE*
re-

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0556916

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Turkey Draw Unit

8. FARM OR LEASE NAME

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 31-24S-22E, NMPM

12. COUNTY OR PARISH 13. STATE

Eddy County

New Mexico

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Franklin, Aston & Fair, Inc.

3. ADDRESS OF OPERATOR

P.O. Box 1090 Roswell, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface 1700' FNL & 2180' FEL, Sec. 31-24S-22E, N.M.P.M.
(SW $\frac{1}{4}$ NE $\frac{1}{4}$)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5828.3 GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

Set surface casing

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On November 17, 1974, 13-3/8", 42#, casing was set at 340' KB with 225 sacks Halliburton lite cement, 5# gilsonite, 1/4# flocele and 150 sacks neat cement, 2% CaCl. Cement did not circulate to surface. After waiting 4 hours, 1" string was run down back side and cemented to surface with one stage of 75 sacks of cement.

After waiting 18 hours, casing and blow out preventer were tested to 500 psi and held for 30 minutes. The cementing work was done by Halliburton.

RECEIVED

NOV 22 1974

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Ernest M. Smith

TITLE

Geologist

DATE

11-19-74

(This space for Federal or State office use)

APPROVED BY

[Signature]

TITLE

DISTRICT ENGINEER

DATE

NOV 22 1974

CONDITIONS OF APPROVAL, IF ANY: