

SULPHATE AUNT #1
SECTION 3, T24S, R27E
EDDY COUNTY, NEW MEXICO

July 19, 1975	Got bit out.
July 21, 1975	Took stem and bit to be shopped
July 22, 1975	Went after stem and bit
July 23, 1975	Made up drill string
July 24, 1975	Drilled clean out.
July 25, 1975	Drilled clean out.
July 26, 1975	Drilled clean out.
July 28, 1975	Drilled clean out to bottom.
July 29, 1975	Drilled 1220' to 1225' in anhy.
July 30, 1975	Down for motor repairs
Aug. 18, 1975	Motor repairs completed
Aug. 19, 1975	Drilled clean out.
Aug. 20, 1975	Drilled clean out.
Aug. 21, 1975	Drilled clean out.
Aug. 22, 1975	Drilled clean out.
Aug. 23, 1975	Drilled clean out.
Aug. 25, 1975	Drilled clean out.
Aug. 26, 1975	Stranded 7/8' drill line
Aug. 27, 1975	Spliced drill line
Aug. 28, 1975	Drilled hole bridged over
Aug. 29, 1975	Drilled
Aug. 30, 1975	Drilled
Sept. 1, 1975	Drilled hole clean to bottom
Sept. 2, 1975	Drilled 1225' to 1230' in anhy.
Sept. 3, 1975	Drilled 1230' to 1235' in anhy.
Sept. 4, 1975	Drilled 1235' to 1240' in anhy.
Sept. 5, 1975	Oil line broke on motors, rod and main bearing possibly ruined. crankshaft.

RECEIVED

OCT 23 1975

O. C. C.
ARTESIA, OFFICE