

SULPAHTE AUNT #1  
SECTION 3, T24S, R27E  
EDDY COUNTY, NEW MEXICO

Sept. 6, 1975	Waiting on parts and working on motor
Sept. 25, 1975	Drilled clean out.
Sept. 26, 1975	Drilled clean out.
Sept. 27, 1975	Drilled clean out.
Sept. 29, 1975	Drilled clean out.
Sept. 30, 1975	Drilled 1240' to 1245' in anhy.
Oct. 1, 1975	Drilled 1245' to 1250' in anhy.
Oct. 2, 1975	Drilled 1250' to 1255' in anhy.
Oct. 3, 1975	Drilled 1255' to 1260' in anhy.
Oct. 4, 1975	Drilled 1260' to 1265' in anhy.
Oct. 6, 1975	Drilled 1265' to 1270' in anhy.
Oct. 7, 1975	Ordered 7/8" line
Oct. 8, 1975	Took off and spooled old 7/8" line
Oct. 9, 1975	Put on new 7/8" line
Oct. 10, 1975	Drilled clean out.
Oct. 11, 1975	Drilled 1270' to 1275' in anhy.
Oct. 14, 1975	Drilled 1275' to 1280' in anhy.
Oct. 15, 1975	Drilled 1280' to 1285' in anhy.
Oct. 16, 1975	Drilled 1285' to 1290' in anhy.
Oct. 17, 1975	Drilled 1290' to 1292' in anhy. V.H. Crevice not letting tools work
Oct. 20, 1975	Drilled 1292' to 1293' in anhy. V.H. Crevice still hurting drilling
Oct. 21, 1975	Drilling out crevice.
Oct. 22, 1975	Drilling out crevice.
Oct. 23, 1975	Drilling out crevice.
Oct. 24, 1975	Drilling out crevice.
Oct. 25, 1975	Drilling out crevice.
Oct. 28, 1975	Drilling out crevice.
Oct. 29, 1975	Drilling out crevice.