

SULPHATE AUNT #1
SECTION 3, T24S, R27E
EDDY COUNTY, NEW MEXICO

Dec. 3, 1975 Picked up new line to splice in.
Dec. 4, 1975 Spliced line.
Dec. 5, 1975 Restrung tools, put on new type bit.
Dec. 6, 1975 Drilled 1299' to 1300' anhy V.H. Worked on engine radiator.
Dec. 8, 1975 Drilled 1300' to 1302' anhy V.H.
Dec. 9, 1975 Drilled 1302' to 1303' anhy V.H. Strand came out of splice.
Dec. 10, 1975 Reworking line.
Dec. 11, 1975 Reworking line.
Dec. 12, 1975 Finished line work.
Dec. 13, 1975 Drilled 1303' to 1305' anhy V.H.
Dec. 15, 1975 Drilled 1305' to 1307' anhy V.H.
Dec. 16, 1975 Drilled 1307' to 1309' anhy V.H.
Dec. 17, 1975 Drilled 1309' to 1312' anhy V.H.
Dec. 18, 1975 Drilled 1312' to 1314' anhy V.H.
Dec. 19, 1975 Drilled 1314' to 1316' anhy V.H.
Dec. 20, 1975 Drilled 1316' to 1317' anhy V.H.
Dec. 22, 1975 Drilled 1317' to 1318' anhy V.H.
Dec. 23, 1975 Drilled 1318' to 1320' anhy V.H.
Jan. 6, 1976 Drilled 1320' to 1322' anhy V.H.
Jan. 7, 1976 Drilled 1322' to 1323' anhy V.H.
Jan. 8, 1976 Drilled 1323' to 1325' anhy V.H.
Jan. 9, 1976 Drilled 1325' to 1326' anhy V.H.
Jan. 10, 1976 Drilled, -stem cracked at box, bit came unscrewed.
Jan. 12, 1976 Fishing for bit.
Jan. 13, 1976 Fishing for bit.
Jan. 14, 1976 Fishing for bit.
Jan. 15, 1976 Fishing for bit.
Jan. 16, 1976 Fishing for bit.
Jan. 17, 1976 Fishing for bit.