## SULPHATE UNCLE SECTION 23, T24S, R27E EDDY COUNTY, NEW MEXICO

- Nov. 21, 1975 Drilled 2009 to 2010 in anahydrite.
- Nov. 24, 1975 Drilled 2010 to 2012 in anahydrite.
- Nov. 25, 1975 Drilled 2012 to 2014 in anahydrite.
- Nov. 26, 1975 Drilled 2011, to 2015 in analydrite.
- Nov. 27, 1975 Drilled 2015 to 2017 in anahydrite.
- Dec. 1, 1975 Drilled, worked on sand reel clutch.
- Dec. 2, 1975 Repairing sand reel

ί

- Dec. 3, 1975 Repairing sand reel.
- Dec. 4, 1975 Repairing sand reel.
- Dec. 5, 1975 Repairing sand reel.
- Dec. 8, 1975 Repairing sand reel.
- Dec. 9, 1975 Drilled 2017 to 2018 in anahydrite, broke main shaft.
- Dec. 10, 1975 Ordered Parts, cannot get definite shipping date on parts.
- Dec. 30, 1975 Rec'd partial order on parts.
- Dec. 31, 1975 Worked on shaft.
- Jan. 2, 1976 Worked on shaft.
- Jan. 3, 1976 Worked on shaft.
  - Jan. 4, 1976 Worked on shaft.
  - Jan. 5, 1976 Worked on shaft.
  - Jan. 6, 1976 Norked on shaft.
  - Jan. 7, 1976 Waiting on balance of parts.
  - Jan. 8, 1976 Cannot get shipping date on parts.
  - Jan. 9, 1976 No parts.
  - Jan. 22, 1976 No parts so starting tearing down rig.
  - Jan. 23, 1976 Rigged down,
  - Jan. 26, 1976 Moved out.

(

- Jan. 27, 1976 Moved new rig in.
- Jan. 28, 1976 Rigged up.

Jan. 29, 1976 Rigged up.

RECEIVED

FEB 1 2 1976

O. C. C.