

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

FORM NO. 42-R1424
(Other instructions on reverse side)

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Coquina Oil Corporation	8. FARM OR LEASE NAME Federal
3. ADDRESS OF OPERATOR 200 Bldg. of the S.W., Midland, Texas 79701	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any state requirements. See also space 17 below.) At surface 1730' FNL & 1980' FWL Sec. 20	10. FIELD AND POOL, OR WILDCAT Und. Morrow
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 20 T-23-S R-26-E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3410 G.L.	12. COUNTY OR PARISH 13. STATE Eddy New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREAT ☐

MULTIPLE COMPLETE ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOT OR ACIDIZE ☐

ABANDON* ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT* ☐

REPAIR WELL ☐

CHANGE PLANS ☐

(Other) Int. csg & T.D. ☒

(Other) ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled a 12 1/4" hole to 2900'. Ran 72 jts 8 5/8" 24# & 32# J-55 STC 8rd csg set @ 2899'. Cemented w/800 sxs, Lite Wate + 200 sxs Class C w/2% CaCl₂ & 1/4# Flocele in all cement. Pumped plug down @ 6:25 p.m., 1-18-75 w/185 BFW. Ran temp. survey. TOC 1100'. Ran 1" to 1102'. Spotted 500 sxs Class H. Ran 1" to 1055'. Spotted 162 sxs Class H w/3% CaCl₂ + 338 sxs Class H. Ran 1" to 1025'. Spotted 160 sxs Class C w/3% CaCl₂ + 340 sxs Class C. Ran 1" to 1015'. Spotted 100 sxs Class C w/3% CaCl₂. Ran 1" to 992'. Spotted 100 sxs Class C w/3% CaCl₂. Ran 1" to 992'. Spotted 200 sxs Class C plus 100 sxs Class C w/3% CaCl₂. Ran 1" to 672'. Spotted 200 sxs Class C w/2% CaCl₂ plus 100 sxs Class C. Cement circ. WOC 18 hrs. Tested csg to 1000 psi. Drilled a 7 7/8" hole to 11,820'. Log's and DST's indicated no commercial production. Prep tp P&A.

RECEIVED

MAR 17 1975

O. C. C.

ARTESIA, OFFICE

RECEIVED
MAR 14 1975
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED D.C. Radtke TITLE Engineer DATE 3-13-75

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

APPROVED
MAR 14 1975
L. BECKING
ARTESIA DISTRICT ENGINEER