



=====Transposition of the pressure recorder charts=====



=====Transposition of the pressure recorder charts=====



The preceding is a transposition of the pressure recorder charts covering test to the blowout control equipment in service on your well drilling in the Sitting Bull Falls, New Mexico Area, Midland District, Texas. Test was made with test plug landed in casing head with the following test results:

Arrived location - rig nipping up.

TESTING: Blind Rams with valve closed next to stack on chokeline - pressure applied thru test entry at end of kill line. Valve next to stack on chokeline very hard to operate.