

Details of bop test

American Quasar


Huber State #1

2/11/75


Contractor: Ard Drlg. Rig 7

Test by Yellow Jacket Tools and Services, Inc.

=====Transposition of the pressure recorder charts=====



=====Transposition of the pressure recorder charts=====



The above is a transposition of the pressure recorder charts covering test to the blowout control equipment in service on your well drilling in the Sitting Bull Falls, New Mexico Area, Midland District, Texas. Test was made with test plug landed in casing head with the following test results:

Arrived location - rig changing rams.

TESTING: Blind Rams with valve closed next to stack on kill line, outlet valve closed