

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPL. TP\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-326

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry

2. NAME OF OPERATOR

American Quasar Petroleum Co. of New Mexico

3. ADDRESS OF OPERATOR

606 Vaughn Bldg, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)

At surface  
1980' FN&EL, Section 9, T23S, R23E

7. UNIT AGREEMENT NAME

Tippin Ranch Unit

8. FARM OR LEASE NAME

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 9, T23S, R23E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4156' GR

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☒ Rng casing

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

13 3/8" casing

Cemented H-40 48# 13 3/8" casing at 400' with 400 sx Class C cement - cement circulated. WOC 24 hours - pressure tested to 1000 # - held OK. PD 8:45 PM 3-22-75.

8 5/8" casing

Cemented 24# & 32# K-55 8 5/8" casing at 2462' with 950 sx H. L. W. w/5# Gilsonite & 1/4# Flocele followed w/ 200 sx "C" w/2% CaCl - cement circulated. WOC 24 hours - pressure tested to 2000# - held OK. PD 10:15 PM 3-30-75.

RECEIVED

U.S. DEPT. OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
MIDLAND, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Lynn D. Jones

TITLE

Div. Operations Mgr.

DATE

10-24-75

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

OCT 28 1975

WEEK