

UNITED STATES **N. M. O. C. C.**
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.
NM-0415688-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

OLD INDIAN DRAW UNIT

8. FARM OR LEASE NAME

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

INDIAN DRAW-DELAWARE

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

18-22-28 NMPM

12. COUNTY OR PARISH

EDDY

13. STATE

N.M.

1. OIL WELL ☐ GAS WELL ☐ OTHER **DRILLING**

2. NAME OF OPERATOR

AMOCO PRODUCTION COMPANY 79714 AMOCO PRODUCTION COMPANY

3. ADDRESS OF OPERATOR

BOX 367, ANDREWS, TEXAS 79714

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

2002' FSLX1721' FWL Sec.18 (UNIT K, NE1/4 SW1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3088' G.L.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other)

SPUDDING

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

**Byrd Hrg Co. spudded 12 1/4" hole 5:30m 9-3-75.
on 9-4-75, 8 5/8" OD 24" K-55 STC Casing was set
@ 388' w/ 350 Sx Class C + 2% PACLZ. Cement Circ (93 Sx).
After 18 hours, tested casing w/ 1000 psi
for 30 min. Test O.K.
Reamed hole to 7 7/8" @ 388' and resumed drilling.**

RECEIVED

SEP 10 1975

O. C. C.

ARTESIA, OFFICE

RECEIVED

SEP - 8 1975

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Lois R. Roakum

TITLE ADMINISTRATIVE ASSISTANT

DATE

9-5-75

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY

TITLE

DATE

*See Instructions on Reverse Side

4- USGS-ART

1- DIV

1- SUSA

1- RIV

2- BASS

1- MARATHON