

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLI
(Other Instructions
verse side)

E*
re-

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM 23269	
2. NAME OF OPERATOR MONSANTO COMPANY		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 321 West Texas, Midland, Texas 79701		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1844' FSL & 2140' FWL		8. FARM OR LEASE NAME ROBINIA DRAW	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4020 Gr; 4037 DF		10. FIELD AND POOL, OR WILDCAT WILDCAT	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 3 T-23S, R-24E	
		12. COUNTY OR PARISH Eddy	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled 12 1/2" hole to 2500';
Set 9 5/8" 36# K-55 LT&C Casing at 2500'; Cmt'd w/ 1000 Sx. Lite + 150 Sx. Class "C"
cement; Plug down @ 6:30 PM 9/3/75. Cement did not circulate; Ran 1" in annulus;
Cemented to surface w/ 700 Sx. in 3 stages.

WOC 24 Hrs. & tested w/ 1000 psi for 30 Mins., Held OK.

RECEIVED

RECEIVED

SEP 15 1975

SEP 12 1975

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

O. C. C.
ARTESIA, OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Regional Production Mgr.

DATE 9/11/75

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side