Form 3160-5 (November 1983) (Formerly 9-331)  DEPARTMENT OF THE INTERIOR **erse** side)  Tellow **Tree **Interior**  Tellow **Tree **Tr	Budget Bureau No. 1004-0135 Expires August 31, 1985  5. LEABE DESIGNATION AND SELIAL NO.
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)	NM-0556857  6. IF INDIAN, ALLOTTES OR TRIPE NAME
OIL GAB WELL X OTHER	7. CNIT AGBERMENT MAME Nash Unit
2. NAME OF OPERATOR Mesa Operating Limited Partnership JAN 07'88	8. FARM OR LEASE NAME Nash Unit
P.O. Box 2009, Amarillo, Texas 79189 O. C. D.	9. WBLL NO. #2
1. LOCATION OF WELL (Report location clearly and in accordance with any State requirements).  See also space 17 below.)  At surface  1350' FNL/1980' FWL	Nash Draw Atoka  11. sec., T., E., M., OR BLE. AND SURVEY OR AREA  Sec. 18-23S-30E
14. PERMIT NO.   15. ELEVATIONS (Show whether DF, RT, GR, etc.)  API # 30-015-21672   3039 *	12. COUNTY OR PARISH 13. STATE Eddy NM
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Ot	ther Data
NOTICE OF INTENTION TO: SUBBEQUENT REPORT OF:	
TEST WATER SHUT-OFF  FRACTURE TREAT  SHOOT OR ACIDIZE  REPAIR WELL  (Other)  The street of the stree	of multiple completion on Well tion Report and Log form.)
MI & RU Western Co. on 12/14/87 - acidized Atoka Bank perfs 4000 gals 15% NEFE acid. Returned well to production 12/18/8 pressure buildup for 24 hours, put well on intermitter - 3 off. Tested 12/24/87 @ 68 MCF, 0 BO, 0 BW, FTP 250, ck 12/	87. Well shut in for hours on and 9 hours 64".
xc: BLM-Carlsbad (0+5), NMOCD-A, Regulatory, Prod Rcds, Expl., P.	artners
SIGNED CELLEN (LE IN MEANE) TITLE Regulatory Analyst	1/6/88
(This space for Federal or State office use)  APPROVED BY	DATE