

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0415688-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ DRILLING APR 27 1976

2. NAME OF OPERATOR
AMOCO PRODUCTION COMPANY ✓

3. ADDRESS OF OPERATOR
BOX 367, ANDREWS, TEXAS 79714

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1017' FSHY 1973' FWL Sec. 18 (Unit N, SE 1/4 SW 1/4)

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3078' GL

7. UNIT AGREEMENT NAME

OLD INDIAN DRAW

8. FARM OR LEASE NAME

OLD INDIAN DRAW UNIT

9. WELL NO.

8

10. FIELD AND POOL, OR WILDCAT

INDIAN DRAW- DEL

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

18-22-28 NMPM

12. COUNTY OR PARISH 13. STATE

EDDY N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐
(Other) ☐

WATER SHUT-OFF ☒ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☒
(Other) Spruading
(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Capitan Oreg Co. spruaded 12 1/4" hole 11:PM 4-19-76.
On 4-20-76, 10 3/4" 40.48" casing was set at 438'
w/ 500 Sx Class C + 2% CACL2. Circ. 75 Sx. Woe 18 hours.
Tested casing w/ 500psi for 30 min. Test OK.
Reduced hole to 7 7/8" @ 438' and resumed drilling.

* 8BT J-55 ST#C

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

ADMINISTRATIVE ASSISTANT

DATE

4/27/76

APPROVED BY

CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE

0+4- USGS-ART
1- DIV
1- SUSP
1- R24
2- BASS

APPROVED
APR 25 1976
L. L. BECKMAN
DISTRICT ENGINEER

* See Instructions on Reverse Side

RECEIVED

APR 23 1976

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO