	C C C COPY	CISF
Form S-RECEIVED UNI®SD STA	E INTERIOR Verse side)	Form approved. Budget Bureau No. 42-R1424 5. LEASE DESIGNATION AND BERIAL NO
APR 21 1980 GEOLOGICAL S		NM 17589
SUNDRY NOTICES AND RE	PORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR THIBE NAME
Op Gt D, this form for proposals to drill or to de	epen or plug back to a different reservoir.	
I. ARTESIA, OFFICE	RECEIVE	7. UNIT AGREEMENT NAME
OIL CAB WELL OTHER Dry Hole		S. FARM OR LEASE NAME
Mesa Petroleum Co.	AUC 1 2 10-	
3. ADDRESS OF OPERATOR	ARTERIA COLOGICAL SUC	9. WELL NO.
1000 Vaughn Bldg., Midland, 4. LOCATION OF WELL (Report location clearly and in accordance)	TX 79701 "TESIA NEW MEXICO	Nash Unit 9. WELL NO. 7 5 10. FIELD AND POOL, OR WILDCAT Undesignated
See also space 17 below.) At surface		Undesignated
2310' FSL & 330' FEL	of Section 13	11. SEC., T., R., M., OE BLK. AND SURVEY OR AREA
		Sec 13, T23S, R29E
	how whether DF, RT, GR, etc.)	12. COUNTY OB PARISH 13. STATE
3015'		Eddy NM
16. Check Appropriate Box To	o Indicate Nature of Notice, Report, or C	
NOTICE OF INTENTION TO:	scbsząc	JENT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASE	NG WATER SHUT-OFF	ALTERING CASING
FRACTURE TREAT MULTIPLE COMPLETE SHOOT OR ACIDIZE ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT [•]
REPAIR WELL CHANGE PLANS	(Other)	of multiple completion on Well
(Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly sta	Completion or Recompl	including estimated date of starting any
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stapproposed work. If well is directionally drilled, give a nent to this work.)* 	ubsurface locations and measured and true vertica	al depths for all markers and zones perti-
Well was drilled to total de	p_{1} of 5100' on 7-27-76	Drill stem test and
electric logs indicated the	well was non-commercial.	After verbal approval
from Jim Knauf, USGS the we	ell was plugged and aband	oned as follows:
Spotted 60 sx Class "H"	4 900'-4.750' across t/	Cherry Canvon
60 sx Class "H"	3,210'-3,060' across 8-	5/8" shoe at 3,160'
Set CIBP @	3,002'	1t costions
267 sx Class "H" 267 sx Class "H"		lt sections lt section
267 sx Class "H"		lt section
DOsx at surface No attempt was mad	e to null casing	
Mud of 9.1 PPG was spotted b	etween all cement plugs.	Installed dry hole
marker. Plugging operations	were completed 7-28-76.	
	· · ·	
18. I hereby certify that the foregoing is true and correct		
Michael P M. to	TITLE Division Engineer	DATE JULY 29, 1976
(This space for Federal or State office use) Groupe H. STEWART		066° 5 mm
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE
*0		

*See Instructions on Reverse Side

XC: JLF, MEC, JWH, 5-NMOCC, 10-WI Partners, LMC, File