

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-17412

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

JAN 12 1977

1. OIL WELL ☐ GAS WELL ☐ OTHER Dry

2. NAME OF OPERATOR
American Quasar Petroleum Co. of New Mexico

3. ADDRESS OF OPERATOR
1000 Midland National Bank Tower, Midland, Tx 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
2080' FNL & 2105' FEL of Section 12

7. UNIT AGREEMENT NAME
Robinia Draw Unit8. FARM OR LEASE NAME
Robinia Draw Unit

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Ud. Robinia Draw-Morrow Gas

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 12, T-23S, R-23E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4206' GR

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐

PULL OR ALTER CASING

☐

FRACTURE TREAT

☐

MULTIPLE COMPLETE

☐

SHOOT OR ACIDIZE

☐

ABANDON*

☒

REPAIR WELL

☐

CHANGE PLANS

☐

(Other)

☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐

REPAIRING WELL

☐

FRACTURE TREATMENT

☐

ALTERING CASING

☐

SHOOTING OR ACIDIZING

☐

ABANDONMENT*

☐

(Other)

☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to set the following cement plugs 7-22-76:

50 sx plug	9950-9800'
50 sx plug	8200-8050'
50 sx plug	6400-6250'
35 sx plug	4800-4700'
35 sx plug	2550-2450' across 8 5/8" shoe
10 sx plug	Surface of 8 5/8" casing

RECEIVED

JUL 29 1976

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct.

SIGNED

Lynn D. Jones

TITLE Div. Operations Mgr.

DATE 7-21-76

(This space for Federal or State office use)

APPROVED BY

TITLE

ACTING DISTRICT ENGINEER

DATE JAN 11 1977

CONDITIONS OF APPROVAL, IF ANY: