

N. M. O. C. C. COPE
UNIT STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLIC.
(Other instructions on reverse side)Copy to SF
Form approved.
Budget Bureau No. 42 R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0415688-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or re-drill for purposes of a different reservoir.
Use "APPENDIX C" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR **AMOCO PRODUCTION COMPANY**

3. ADDRESS OF OPERATOR **P.O. DRAWER A, LEVELLAND, TEXAS 79555**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
1001' FNL x 2289' FEL, Sec. 18 (UNIT B NW/4 NE/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3081.6 GL

7. UNIT AGREEMENT NAME

OLD INDIAN DRAW UNIT

8. FARM OR LEASE NAME

OLD INDIAN DRAW UNIT

9. WELL NO.

15

10. FIELD AND POOL, OR WILDCAT

INDIAN DRAW DELAWARE

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

18-22-28 NMPM

12. COUNTY OR PARISH

EDDY

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐PULL OR ALTER CASING ☐WATER SHUT-OFF ☐REPAIRING WELL ☐FRACTURE TREAT ☐MULTIPLE COMPLETE ☐FRACTURE TREATMENT ☐ALTERING CASING ☐SHOOT OR ACIDIZE ☐ABANDON* ☐SHOOTING OR ACIDIZING ☐ABANDONMENT* ☐REPAIR WELL ☐CHANGE PLANS ☐(Other) ☐CORE ☒(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Reached core point 3296' at 10:00 PM 1-13-77. Core No. 1 3296'-3356' Delaware Sand. Recovered 60 ft. of cores as follows: 2 1/2 ft. - Shaly Fossiliferous Dense Limestone; 20 1/2 ft. - Fine Grained Friable Sandstone, Slightly Shaly in upper 6 1/2 ft, good Permeability in remainder, oil bleeds occurring throughout interval 3298.5' to 3319'; strong oil odor, bright yellow fluorescence, crumbled and broken 3305.5' to 3306.5'; 29 ft - same Clean Friable Sandstone with occasional faint odor and slight spotted fluorescence scattered through interval, lower 9 ft of different appearance with lesser permeability and possibly water-bearing; 8 ft. Silty Fossiliferous Limestone or Limy, Shaly, Dense, Very Fine Grained Sand, No Shows.

18. I hereby certify that the foregoing is true and correct

SIGNED

Ray W. Cox

TITLE

Administrative Assistant

DATE

2-4-77

(This space for Federal or State office use)

APPROVED BY

Lee J. Lora

TITLE

ACTING DISTRICT ENGINEER

DATE

FEB 7 1977

CONDITIONS OF APPROVAL, IF ANY:

064-NMOCC-AAT

1-Div.
1-Susp.
1-RC
2-Bass
1-Marathon

*See Instructions on Reverse Side