

NMCC COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		RECEIVED		5. LEASE DESIGNATION AND SERIAL NO. NM-4600	
2. NAME OF OPERATOR Harvey E. Yates Company ✓		APR 5 1978		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P. O. Box 1933, Roswell, New Mexico 88201		O. C. C.		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' FNL & 1980' FWL		ARTESIA, OFFICE		8. FARM OR LEASE NAME China Canyon ARCO Federal	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3878' GL		9. WELL NO. 1	
				10. FIELD AND POOL, OR WILDCAT Wildcat	
				11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 28, T-23S, R-24E	
				12. COUNTY OR PARISH Eddy	
				13. STATE N. M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	FRACTURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	SHOOTING OR ACIDIZING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other) Commence operations	<input checked="" type="checkbox"/>
(Other)	<input type="checkbox"/>	(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

2-28-78 Spudded 9:00 am.

3-22-78 Drilling at 359'.

RECEIVED
MAR 31 1978
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Clark T. Harder TITLE EngineerDATE 3-27-78

(This space for Federal or State office use)

APPROVED BY Joe D. Lara TITLE ACTING DISTRICT ENGINEERDATE APR 4 - 1978

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side