

1 - Getty Oil Co. Attn: H.D. Woods, Jr.  
Box 1231 Midland, TX 79702

Moved in service unit 9/8/78. Ran tbg. and bit and tag top of cement fill at 12,961'. 390' cement was circulated. Drill out cement 12,961' to 13,306'. PBTD 13,306'. Tested casing with 1500# for 30 minutes. Test ok.

Perforated Morrow zone 12,534'-12,552' with 4 JSPF. Ran Baker model D packer and set at 11,159'. Ran 1300' of 2-3/8" tubing as tailpipe and hydrotest in hole w/6000#. Ran 2-7/8" tubing and hydrotested in hole w/6000#. Test ok. Latched into packer. Ran wireline and recovered blanking plugs 11,153' to 11,398'. Swabbed well. Recovered 30 BLW and well started flowing. Flow testing well.