NO. OF COPIES RECEIVED DISTRIBUTION	Form C-103 Supersedes Old
SANTA FE I NEW MEXICO OIL CONSERVA PORECOMMISSION E D	C-102 and C-103 Effective 1-1-65
NOV 8 1979	5a. Indicate Type of Lease State X Fee
OPERATOR	5. State Ctl & Gas Lease No. L 3358
SUNDRY NOTICES AND REPORTS ON WELLS	
1. OIL GAS WELL OTHER-	7. Unit Agreement Name
2. Name of Operator Mesa Petroleum Co	B. Farm or Lease Name Nash Unit
3. Address of Operator 1000 Vaughn Building / Midland, Texas 79701	9. Well No. 7
4. Location of Well UNIT LETTER D	10. Field and Pool, or Wildcat Und. Nash Draw-Morrow
THE West LINE, SECTION 18 TOWNSHIP 235 RANGE 30E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 3012 GR	12. County Eddy
16. Check Appropriate Box To Indicate Nature of Notice, Report or Oth NOTICE OF INTENTION TO: SUBSEQUENT	
PERFORM REMEDIAL WORK	ALTERING CASING
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JQB	PLUG AND ABANDONMENT
OTHER	
17. Ensitie Frepred of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) set Rule Trans. This report is being filed simultaneously with federal form 9-331 as the bottom hole location may be on federal land. Reached depth of 11,111' on 10-17-79. Bottom hole location at 11,060' is 1059' north and 181' west of surface location (685' FNL & 1295' FWL Sec 18, T235, R30E). Thus BHL is located approximately 380' FSL and 1115' FWL of Sec 7, T235, R30E, and is presently on state minerals. The 12-1/4" hole was logged, then 9-5/8" casing run on 10-20-79 as follows: 4673.71' (107 jts) 9-5/8" 47# S95 LTC (btm) 6471.10 (151 jts) 9-5/8" 43.5# S95, LTC 11,144.81 (258 jts) set at 11,111' RKB with collar at 11,050' and DV tools at 6511' and 3728'. Circ 4-1/2 hrs with casing on bottom - full returns. Cement through shoe with 1450 sx LW + 0.3% D-19 + 0.2% R-5 + 1/4# celloflake (mixed at 12.49 ppg, yield 1.94/cu. ft.) followed by 400 sx class "H" + 0.2% HR-5 (mixed at 15.7 ppg, yield 1.17/cu. ft.). Lost returns while displacing. PD at 10:40 AM 10-21-79. Opened DV tool at 6511' and attempted to circulate without success. Closed hydril and reverse circulated down annulus and up 9-5/8" casing for 7 hours. Did not recover any cement. Cement down 9-5/8" and thru DV tool at 6511' with 1350 sx LW + 0.5% D-19 + 1/4# celloflake (mixed at 12.4 ppg, yield 1.97/cu. ft.) followed by 200 sx class "H" displacing. PD at 10:40 AM 10-21-79. No returns while cementing. PD at 11:30 PM 10-21-79. Opened DV tool at 3728'. Pumped 20 bbls mud through DV tool at 3728' but did not regain returns. Closed hydril and reverse circ down annulus and up 9-5/8" casing for 11 hours. Did not recover any cement. Attempted to pump down 9-5/8" casing, unable to (cont.)	
REMANDE Regulatory Coordinator	November 7, 1979
SEFACUED BY Mine Withows TITLE OIL AND GAS INSPECTURE	NOV 2 8 1979

.....

----