Form 9–331
Dec. 1973

...O.D. COPY

Form Approved.
Budget Bureau No. 42–R1424

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)

1. oil well ☐ gas well ☒ other	**NOV 19 1979**	

2. NAME OF OPERATOR
Amoco Production Company

O. C. C.
ARTESIA, OFFICE

3. ADDRESS OF OPERATOR
P. O. Box 68, Hobbs, NM 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)1650' FSL x 1980' FEL, Sec. 20
AT SURFACE:
AT TOP PROD. INTERVAL: (Unit J, NW/4 SW/4)
AT TOTAL DEPTH:

5. LEASE
NM-0415239-b

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Federal AE

9. WELL NO.
1

10. FIELD OR WILDCAT NAME
Und. Morrow

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
20-22-28

12. COUNTY OR PARISH
Eddy

13. STATE
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3077.0 GR

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐		☒
FRACTURE TREAT	☐		☐
SHOOT OR ACIDIZE	☐		☐
REPAIR WELL	☐		☐
PULL OR ALTER CASING	☐		☐
MULTIPLE COMPLETE	☐		☐
CHANGE ZONES	☐		☐
ABANDON*	☐		☐
(other)_____			

(NOTE: Report results of multiple completion or zone change on Form 9–330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 10-19-79 Cactus Drilling Co. (Rig #15) spudded 20" hole at 3:00 A.M. Drilled to a TD of 390' and ran 16" casing set at 390'. Cemented with 575 sx Class C cement with 2% CACL. Plugged down at 8:15 10-21-79. Circulated 100 sx. WOC 18 hrs. Tested casing with 1000# for 30 min. Test OK. Reduced hole to 14-3/4" and resumed drilling.

RECEIVED

NOV 16 1979

U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct
SIGNED _Bob Davis_ TITLE Assist. Admin. Ana. DATE 11-12-79

(This space for Federal or State office use)
ACTING DIST... CT ENGINEER
APPROVED BY _____ TITLE _____ DATE **NOV 16 1979**
CONDITIONS OF APPROVAL, IF ANY:
0+4 USGS-A, 1-Hou, 1-Susp, 1-BD, 1-Marathon, 1-Bass

*See Instructions on Reverse Side