

Form 9-331  
Dec. 1973Form Approved.  
Budget Bureau No. 42-R1424UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well otherU.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

2. NAME OF OPERATOR

Amoco Production Company

3. ADDRESS OF OPERATOR

P. O. Box 68 Hobbs, NM 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1650' FSL &amp; 1980' FEL, Sec. 20

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH: (Unit J, NW/4, SW/4)

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

## REQUEST FOR APPROVAL TO:

## SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐☐FRACTURE TREAT ☐☐SHOOT OR ACIDIZE ☐☒REPAIR WELL ☐☐PULL OR ALTER CASING ☐☐MULTIPLE COMPLETE ☐☐CHANGE ZONES ☐☐ABANDON\* ☐☐

(other)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Pulled tubing and packer. Ran a cast iron bridge plug set at 12300'. Perforated 11720'-724', 12014'-017'; 12020'-033', 12200'-202', with 4 JSPF. Ran tubing, packer, and tailpipe. Packer set at 10199'. Tailpipe at 11605'. Flow tested 1 day. Currently shut-in for pressure evaluation.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

Bob Davis

TITLE

Admin. Analyst

DATE

4-9-80

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

0+4-USGS-A

1-Hou

1-Susp

1-BD