

Guitar Estate #1
Drilling Operations

6/28/80 PU & RIH w/bit, DC's & 289 jts 2 3/8" tbg to top of liner @ 9036'.
6/29/80 Break circ w/reverse unit. Circ hole w/fresh wtr.
6/30/80 PU & RIH w/2 3/8" tbg.
7/1/80 Drld cmt @ 12,439'.
7/2/80 Drld cmt from 12,439' to landing collar @ 12,539'. RU Howco & wash liner & tbg. RD Howco. POOH.
7/3/80 RU Schlumberger. GR tool failed while running CBL-GR-CCL.
7/4/80 RU Schlumberger. Ran CBL-GR-CCL 12,546-11,500'.
7/5/80 No Report.
7/6/80 No Report.

7/7/80 No Report.

7/8/80 Perf Lower Morrow 12,509-12,536'. Set pkr 12,475'.
7/9/80 TIH w/306 jts 2 3/8" N-80 tbg.
7/10/80 RU & swbd. Turned to separator. Flwd 16 hrs. FTP 2750 psi. 14/64" ck.