

GUITAR ESTATE #1
LOVING (MORROW) FIELD
EDDY CO., NEW MEXICO

<u>DST #1</u>	<u>6340'--6545'</u>
IHP	3308 psi
5 min IFP	156-175 psi
60 min ISIP	865 psi
60 min FFP	56-195 psi
120 min FSIP	904 psi
FHP	3327 psi
BHT	118°F
Sample Chamber:	110 psi, 35 ft ³ gas
Recovery:	350' gas cut drilling mud

<u>DST #2</u>	<u>12090'--12278'</u>
IHP	7401 psi
5 min IFP	1190-1258 psi
60 min ISIP	7163 psi
52 min FFP	1393-3791 psi
90 min FSIP	7265 psi
FHP	7333 psi
Sample Chamber:	2600 psi, 1.45 ft ³ gas & 2000 cc mud

DST results no good due to washed out tool joint.

<u>DST #3</u>	<u>12370'--12500'</u>
IHP	7518 psi
5 min IFP	3526-3174 psi
90 min ISIP	5273 psi
60 min FFP	3321-4063 psi
120 min FSIP	5258 psi
FHP	7330 psi
BHT	190°F
Sample Chamber:	2905 psi, 10 ft ³ gas, no fluids

Opened tool @ 10:30 AM for 5 min IF w/good blow. Increased to 500# in 5 mins. SI for 60 mins. GTS in 6 mins. Opened tools for 60 min FF w/strong blow. Pressure increased & stable in 30 mins @ 2200 psi on 3/8" ck.